Appendix –XI

BUILDING SAFETY CERTIFICATE

No. Dated: 08/09/2026

Certified that the existing building **Nayapara English Medium H.S School** at Kadamtala Road , North Nayapara, Dharmanagar, North Tripura comprised of Nil basement(s) and 5 Nos (Permanent and Semi Permanent Structures) blocks (owned/ occupied by School Authority of **Nayapara English Medium H.S School** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (R&B), Govt of Tripura, on 8th Sep 2026 in the presence of **Gokul Ch. Debnath**, Principal, **Nayapara English Medium H.S School** and that the building/premises is found to be **fit** for occupancy up to Class XII with effect from 8th Sep 2026, for a period of **Two year**, subject to compliance with the specific conditions as appended.

1. Any proposed addition, alteration, extension, renovation, or modification to the building shall be carried out only under the supervision of a qualified and competent Engineer. Upon completion of such work, a fresh Structural Safety Certificate shall be obtained from the undersigned before the building is put to use.

2. In the event of any natural calamity, such as flooding, earthquakes, storms, or similar occurrences, or if any signs of structural distress are observed including settlement of foundations, cracks in walls, sagging of roofs, excessive deflection, or any other structural defects the School Authority shall immediately arrange for an inspection by the undersigned or another qualified structural engineer to assess the building's structural stability and safety. Appropriate remedial measures, if required, shall be undertaken before continued occupancy of the building.

Details of Building:-

Sl No.	Name of Block	Type of Building	Year of Construction	Remarks
01	Block- 1	RCC frame Structure, G+1,	2023-24	Structurally sound but Petty maintenance works required , including plastering and painting is required,
02	Block- 2	Load Bearing Structure with GCI Sheet Roofing	1958	Structure is good but petty maintenance works, including ceiling, plastering and painting is required.
03	Block- 3	Load Bearing Structure with GCI Sheet Roofing	1958	Structure is good but petty maintenance works, including ceiling, plastering and painting is required.
04	Block- 4	Load Bearing Structure with GCI Sheet Roofing	1958	Structure is good but petty maintenance works, including ceiling, plastering and painting is required.
05	Block- 5	RCC frame Structure, G+1,	2013	Structurally sound but Petty maintenance works required , including plastering and painting is required,

Issued on **8th Sep 2026** at **04.00** PM by **SDO PWD (R&B), Sub -Division, Dharmanagar, North Tripura.**

08.09.26

SDO, PWD (R & B)
Dharmanagar Sub-Division
Dharmanagar, North Tripura

10.09.26.

(GOKUL CH. DEBNATH)
Principal
H.O & D.D.O.
Nayapara Eng. Med. H.S. School
Dharmanagar, North Tripura
D.D.O. Code : 02035